


SUPER8 50 2T WIRING DIAGRAM



KYMCO



LIGHTING SW

CI	RE	TL	HL	PO
OFF	ON	ON	ON	ON
ON	ON	ON	ON	ON
ON	ON	ON	ON	ON
ON	ON	ON	ON	ON
COLOR	B	BR	L/W	BR/W

START SW

ST	E
FREE	ON
PUSH	ON
COLOR	Y/R

PASSING SW

HI	BAT
PASS	ON
COLOR	L

HORN SW

HO	BAT
FREE	ON
PUSH	ON
COLOR	L

COMB SW

BATT	IG	E	BAT2
LOCK	OFF	ON	ON
COLOR	R	B/W	G

WINKER SW

R	L	WR
L	N	N
R	O	GR
COLOR	SB	O

DIMMER SW

HL	HI	LO
LO	N	O
COLOR	B	L